

The Corporation of the  
Township of Drummond/North Elmsley

# **2014-2019 MULTI-YEAR ACCESSIBILITY PLAN**



## **2017 UPDATE**


## **Barriers addressed in 2017**

### **2017**

1. Filed an accessibility report as required.

#### Barriers Removed:

1. Disposal of Port Elmsley Community Hall



## FERGUSON'S FALLS COMMUNITY HALL

TYPE OF ARRIER	LOCATION	DESCRIPTION	REMEDY	COMPLETION DATE (estimated)	COMMENTS
P	Entrance to Facility	Doors are not automated	Installation of automatic doors	This can be corrected when renovations to the building are done	
P	Entrance to Facility side door	Threshold is not flush; there is a 3 inch graduated lip into the facility	Build a longer graduated sloped entrance	This can be picked up when major renovations to the building are done	The entrance is somewhat sloped and motorized wheelchairs would be able to traverse over it
P	Side Entrance to Facility	Width of exterior door is too narrow at 32"	Use the front entrance as the barrier free entrance	This can be corrected when renovations to the building are done	Should be 33 1/3"
P	Front entrance to facility	The front entrance has a double-door that could accommodate the width of a wheelchair however, the bottom unlocking mechanism for the second door does not work easily and the threshold has a 1 inch lip	construct a sloped ramp into the building	This can be corrected when renovations to the building are done	Choose what entrance is going to be barrier free
P	Hallway to washroom	1½" lip half way down the hallway. The lip is slightly graduated but unassisted access in a manually powered wheelchair might be hard	Graduate the incline	2017	
P	Hallway to washroom	Door frame in hallway is too narrow at 36"		This can be corrected when renovations to the building are done	Hallway should be 43" wide
P	Barrier free washrooms	Bathroom doors have the incorrect door handle	Replace latch door handles	2017	
P	Hallway into the kitchen area	The hallway is too narrow at 38 inches		This can be corrected when renovations to the building are done	Should be 43"



## TOWNSHIP OFFICE

TYPE OF ARRIER	LOCATION	DESCRIPTION	REMEDY	COMPLETION DATE (estimated)	COMMENTS
NO ACCESSIBILITY ISSUES					



## DRUMMOND CENTRE COMMUNITY HALL

TYPE OF BARRIER	LOCATION	DESCRIPTION	REMEDY	COMPLETION DATE (estimated)	COMMENTS
NO ACCESSIBILITY ISSUES					

BARRIER LEGEND: **P** = physical - **C** = communicational - **I**=informational - **T**=technological - **AT** = attitudinal - **A** = architectural - **PL** = policy